



IPX Series



FIRMWARE RELEASE NOTES 1.8.1

RELEASE DATE: 06.2025
RELEASE VERSION: 1.8.1

Version 1.8.1 Contains the following updates:

Features:

- Added flasher color options to the web UI.
- Provides up to 25 priorities for flasher, relay and background screen colors..
- Informacast Speaker description now gets sent as caller ID..
- General Performance Improvements.

Bugs:

- Corrected state that would occasionally not play InformaCast messages
- Zapped a couple bugs.

List of Known Issues:

- Auto-provisioning is not currently activated

Note:

- The default password for units on Firmware Versions 1.6.0 and above has been updated to last 6 digits of Mac address to comply with State of California SB-327.

Note:

- The Half Duplex Intercom feature in InformaCast Advanced will no longer be supported in IPX firmware versions 1.6.4 and above. If help is needed setting up Full Duplex Intercom with InformaCast Advanced, please contact AtlasIED Tech Support for assistance at: 1-800-876-3333 or www.atlasied.com/support

Firmware Update Instructions

Note:

- IPX endpoints on any firmware version prior to 1.0.9 will need to update to version 1.0.9 before updating to version 1.3.1.
- IPX endpoints on any firmware version between 1.0.9 and 1.3.0 will need to be updated to version 1.3.1 prior to updating to version 1.8.1 .
- IPX endpoints on firmware version 1.3.1 or higher can be updated directly to firmware version 1.8.1.

Note:

- When updating IPX endpoints, AtlasIED recommends using the AtlasIED Discover Application.
- Firmware version 1.0.9 (Build# 530) is the minimum required version for update with AtlasIED Discover Application.
- Firmware version 1.2.0 is the minimum required version for updating from the Web UI.

IMPORTANT:

- Do NOT reboot the device during this process until it is fully updated. Multiple reboots may occur automatically as the endpoint installs firmware.

Updating Firmware with the AtlasIED Discover Application

1. Download the AtlasIED Discover Quick Start Guide.
 - The AtlasIED Discover Quick Start Guide can be accessed through the following link: <http://mitk.co/NLD>
2. Download the AtlasIED Discover App IPX Firmware 1.8.1 File
 - The AtlasIED Discover App IPX Firmware 1.8.1 can be accessed through the following link: <http://mitk.co/NLE>
3. Follow the instructions found in the AtlasIED Discover Quick Start Guide.

For additional support contact AtlasIED Tech Support at:
1-800-876-3333 or www.atlasied.com/support

©2025 Atlas Sound LP. The Atlas "Circle A", Soundolier, and Atlas Sound are trademarks of Atlas Sound LP. IED is a Registered Trademark of Innovative Electronic Designs LLC. All rights reserved. All other Trademarks are property of their respective owners. No endorsement is implied. Due to continual product development, specifications are subject to change without notice. ATSO06809 RevH 05/25



1601 JACK MCKAY BLVD.
ENNIS, TEXAS 75119 U.S.A.

TELEPHONE: (800) 876-3333
SUPPORT@ATLASIED.COM

AtlasIED.com