

IPX Series

Firmware Release Notes

Released 10/19/2020

Release version 1.3.1.0 contains the following updates:

Features

- LLDP power negotiation.
- SIP to line out audio.
- Ability to change flasher color on SIP calls.
- Changes to LCD foreground color and LCD background color become active without a reboot.
- Singlewire Advanced half-duplex session. **Note:** The flasher will become active by default as half-duplex requests are priority 0.
- Ability to include multiple InformaCast® server URLs simultaneously in the InformaCast® server URL field.

Bugs

- Fixed an issue causing the device to “pop” and reboot when answering SIP calls.
- Loopback setting changes are automatically saved. Fixes issue where changes did not activate save button and changes would not persist through reboot.
- Fixed Night Ringer registration and stability issues.
- Fixed PoE / PoE+ status on WebUI.
- Ability to change extension on Logic Input 2.
- Fixed SIP and GCK registration status reporting.
- Fixed SIP registration with multiple servers.
- Allow special characters in SIP extensions.
- Allow special characters in SIP authorization secrets.
- Fixed bugs with Display / Strobe Test buttons.
- Fixed IGMPv2 join issues.
- Improvements to IPX functionality with GCK.
- Fixed welcome banner scrolling issues.
- Improvement to NTP time zone settings.
- Other bug fixes and performance improvements.

List of Known Issues

- Auto Provisioning is not currently activated.

Firmware Update Instructions

Note: When updating IPX endpoints, AtlasIED recommends using the AtlasIED Discover Application.

Firmware version 1.0.9 (Build# 530) is the minimum required version for update with AtlasIED Discover Application.

Firmware version 1.2.0 is the minimum required version for updating from the WebUI.

IMPORTANT! Do NOT reboot the device during this process until it is fully updated. Multiple reboots may occur automatically as the endpoint installs firmware.

Updating Firmware with the AtlasIED Discover Application

1. Download the AtlasIED Discover Quick Start Guide
 - i. The AtlasIED Discover Quick Start Guide can be accessed through the following link
https://www.atlasied.com/f/11469/ATS006060B_AtlasIED_Discover_Quick_Start_Guide.pdf
2. Download the AtlasIED Discover App_IPX Firmware 1.3.1.0 File
 - i. The AtlasIED Discover App_IPX Firmware 1.3.1.0 can be accessed through the following link
https://www.atlasied.com/f/12006/AtlasIED%20Discover%20App_IPX%20Firmware1.3.1.0.exe
3. Follow the instructions found in the AtlasIED Discover Quick Start Guide.

For additional support AtlasIED Tech Support can be reached at 1-800-876-3333 or www.atlasied.com/support.