



IPX Series

Firmware Update Guide

Thank you for your purchase of the AtlasIED IPX Speakers

We are continuously making improvements to our IPX speaker features and firmware. In order to make sure your IPX speaker has the latest firmware version please visit www.atlasied.com/ip_enabled_speakers. Select your model and go to Support Files to download the latest firmware version.

Note: IPX endpoints on any firmware version prior to 1.0.9 will need to update to version 1.0.9 before updating to version 1.3.1.

IPX endpoints on any firmware version between 1.0.9 and 1.3.0 will need to be updated to version 1.3.1 prior to updating to version 1.6.0.

IPX endpoints on firmware version 1.3.1 or higher can be updated directly to firmware version 1.6.0.

Once the firmware is downloaded

1. Log into the WebUI via the IP address of the speaker
2. Go to Administration tab
3. Go to Firmware Settings
4. Choose File
5. Speaker will automatically update to the latest firmware and reboot

For questions or support please contact us at 1-800-876-3333 or support@atlasied.com

©2021 Atlas Sound L.P. The Atlas "Circle-A", Soundolier, and Atlas Sound are trademarks of Atlas Sound L.P. IED is a Registered Trademark of Innovative Electronic Designs LLC. All rights reserved. All other Trademarks are property of their respective owners. No endorsement is implied. Due to continual product development, specifications are subject to change without notice. ATSO05938B RevB 5/21 P/N 492360



1601 JACK MCKAY BLVD.
ENNIS, TEXAS 75119 U.S.A.

TELEPHONE: (800) 876-3333
SUPPORT@ATLASIED.COM

AtlasIED.com

